

RECOMMENDATIONS FOR VISITORS

We extend a warm welcome to the Skyworks Solutions facilities in Mexicali, B.C. Below, you will find recommendations to ensure a productive and seamless visit.

UPON ARRIVAL AT THE FACILITY

- Please inform the security personnel of the purpose of your visit and provide the name of the Skyworks employee who will be your contact.
- Present an official identification, which will be retained for the duration of your visit, and you will be issued a VISITOR badge that must be worn visibly at all times.
- All foreign visitors must possess a temporary entry permit issued by INAMI (FMN or FM3). This is a mandatory requirement for access.
- Parking will be assigned upon your arrival.

UPON ENTERING THE BUILDING

- Upon entry, you are required to register any electronic devices with the lobby guard, who will complete a “property registration” form. You must retain this form throughout your visit.

Adhere to the dress code and footwear protocol for entering the facilities and the manufacturing area:

- Closed shoes (maximum heel height of 5 centimeters)
- No shorts, caps, or hats
- Shirts and blouses with sleeves (at least 5 centimeters below the shoulder), no straps.
- Preferably wear pants, or skirts with a maximum length of 5 centimeters above the knee.
- Weapons are prohibited, except for personnel from the valuables transport service.
- The use of cameras or video equipment (both external and internal areas) is not permitted.

UPON ENTERING THE TRANSITION HALLWAYS, PRODUCTION AREA, AND CLEAN ROOM

- From this area onwards, you must adhere to the footwear protocol, which includes wearing shoe covers in the hallways. These shoe covers are provided by the lobby security guard.
- Food is not permitted in these areas.

- In the production area, you must wear overalls and boots (or heel covers), which will be provided by your Skyworks contact.

UPON ENTERING AND STAYING IN THE PRODUCTION AREA AND CLEAN ROOM

- Before entering, please secure your personal items with your contact, as they are not allowed on the production floor (including personal cell phones, tablets, laptops, handbags, jewelry, and any other items not related to the manufacturing process).
- Follow the dress code and footwear protocol as indicated on the informational posters.
- Makeup is considered a contaminant and is therefore not permitted in the production area, without exception.

UPON LEAVING THE FACILITIES

- You must comply with the inspection conducted by security personnel in the lobby, which includes checking bags, backpacks, lunch boxes, briefcases, etc.
- If you registered electronic equipment, verify it with the “property registration” form issued upon entry by the lobby security guard.
- Return the VISITOR-SUPPLIER badge you received upon entry at the entrance booth, and the security guard will return your retained identification.

For further information and assistance during your visit, please contact your Skyworks.

